

Site Safety Inspection for: West Tower - M927
Site Score: 84
Site Manager: Will Davenport

<u>Category</u>	<u>Comment</u>	<u>Score</u>
Site Organisation	Good office set up, very small lay down area Securing plasterboards by banding is good practice for all high rise sites. Extra care taken when bad weather conditions are expected	8.5
Documentation	All up to date, Method statement for work in lift shaft amended on site	8.5
Training	Toolbox talks given on site specific issues	8
Electrical	PAT testing in 2 weeks	8
Plant & Equipment	Reciprocating saw on site	8
Scaffold	None in use	9
PPE	PPE use has improved	8
Access	MFL keeping all access and egress routes clear, access to work areas is by hoist. Difficult access from lay down area to hoist.	9
Housekeeping	Housekeeping is of a good standard, fixers filling waste bins	9
Fire	No issues on site	8
Dangerous Acts	None	
Main Contractor Issues	No issues, safety awareness and implementation is good	8

Inspection carried out by:

Inspection date:

Page of

Signed off by Contracts Director:

Site Safety Inspection for: West Tower M927 Site Score: 84
Site Manager: Will Davenport

<u>Category</u>	<u>Comment</u>
Inspection Details	Dry and fine, 10 fixers, 7 plasterers and 4 labourers on site.
Actions Required:	
Site Organisation	Good practice to be implemented on other sites
Documentation	No actions
Training	No actions
Electrical	No actions
Plant & Equipment	No actions
Scaffold	No actions
PPE	Improved to an acceptable standard
Access	No actions
Housekeeping	No actions
Fire	No actions
Dangerous Acts	No actions
Main Contractor Issues	No issues

Inspection carried out by:

Inspection date:

Page of

Signed off by Contracts Director: